

TT Graph (for Windows) Manual

Table of Contents

Introduction	2
Chapter One: Installing TTGraph For Windows	3
Windows 95	3
Windows 3.1x	5
Chapter Two: Connection to Tonnage Monitors	6
Connect with RS232	6
Connect with both RS232 and RS485	7
Chapter Three: Downloading Signatures.....	9
Downloading from a Com Port.....	9
Downloading from PressNet.....	10
Saving Signatures	11
Opening Signatures	11
Exit and Save View.....	12
Printing Signatures.....	12
Chapter Four: Viewing Signature Windows.....	13
Viewing each corner separately	13
Tile view	13
Cascade view	14
View the Outer	14
View the Inner	15
View the Outer and Inner	15
View degrees and inches (with Resolver).....	16
Three ways to Scale your signatures	16
Scale to Fit	16
Scale Uniformly by Capacity	17
Scale Uniformly by Highest Peak.....	17
Chapter Five: Using Signature Windows	18
How to read signature windows.....	18
How to read Tabular Data.....	18
Tabular Data.....	18
Tabular Data and Signatures together.....	19

Introduction to TTGraph For Windows

TTGraph For Windows software supplies a primary part of the Toledo Transducers Inc. press monitoring system.

TTGraph displays press curves and signals that Toledo Transducers Inc. Tonnage Monitors read.

The program provides Graphical as well Tabular Data for analysis of force from metal forming machines.

In its updated Windows version TTGraph is user-friendly with simple commands and user-ready software.

This user's manual will provide you with the necessary tools to use TTGraph for Windows.

System requirements:

Windows 3.1x or higher

386 PC or higher

4 MB RAM

One unused Com Port or network access to PressNet

RS232 or RS485 interface

Chapter One: Installing TTGraph For Windows

WINDOWS 95

(If you are using Windows 3.1x, please see the next section.)

1. Insert the installation disk into your floppy disk drive. Choose Run in the Start menu. (See Fig. 1)




Figure 1: Run window from the Start menu.

2. Type A:\ setup and hit Return or click on OK. (See Fig.1)
(If A is not your floppy drive, please substitute the appropriate drive letter.)
3. Follow the TTGraph for Windows Installation program.
4. When you have completed the installation, start the program.
5. Choose Directory in Setup on the menu bar.
6. Type appropriate directories for TTGraph and PressNet. (See Fig. 2).




Figure 2: Directory window.

7. Choose Driver in Setup on the menu bar.
8. Choose Add. (See Fig. 2a).
9. Choose your monitor. Then choose OK.(See Fig. 2b).
10. Choose which monitor to use a Default.
11. Then choose OK.




Figure 2a: Driver Window




Figure 2b: Add Driver

WINDOWS 3.1X

(If you are using Windows 95, please skip this section.)

1. Insert the installation disk into your floppy disk drive. Choose Run in the File menu. (See Fig. 3).




Figure 3: Run from the File menu.

2. Type A:\ setup and hit Return or click on OK. (See Fig.3)
(If A is not your floppy drive, please substitute the appropriate drive letter.)
3. Follow the TTGraph for Windows Installation program.
4. When you have completed the installation, start the program.
5. Choose Directory in Setup on the menu bar.
6. Type appropriate directories for TTGraph and PressNet. (See Fig. 2).
7. Choose Driver in Setup on the menu bar.
8. Choose Add. (See Fig. 2a).
9. Choose your monitor. Then choose OK.(See Fig. 2b).
10. Choose which monitor to use a Default.
11. Then choose OK.

Chapter Two: Connection to Tonnage Monitors

TWO CHOICES: RS485 OR RS232

1. Use RS232 to connect one laptop to a tonnage monitor. (*See this section*).
2. Use RS485 for plant wide connections. (*See following section*).

Connect with RS232 connector (See Fig. 4)

(*If you are using the RS485 connection, please go to next section.*)

- The RS232 uses either a 9 pin or 25 pin connector. The 9 pin is most common.
- The RS232 is used to attach one monitor to one computer.
- The RS232 is commonly used for laptop or portable computers.
- The RS232 cable length is limited to 50 ft.

Connect to computer:

1. Locate one serial Com port often in the back of the PC. Be sure it matches your connector. (I.E. A 9 pin connector should be connected to a 9 pin Com port.)

(*Note: Com 1 is the TTGraph for Windows default port, but can easily be changed when downloading signatures. See page 5.*)

Connect to Monitor

Please see your respective installation manuals to attach RS232 to the N260, Quick-Learn, TQM or PW monitors.




Figure 4: RS232 connection.

Connect with both RS485 and RS232 connection

R+	Blue / White	TX 422 -	Out
R -	Blue	TX 422 +	Out
Ground	G & G / White	Common	
T -	Orange	RX 422 + / 232	In
T +	Orange / White	RX 422 -	In
From SENCON		To Computer	9 Pin Connector
RX 232	Blue	Pin 2	Receive
TX 422+ / 232	Red	Pin 3	Transmit
G (ground)	Green	Pin 5	Ground
From SENCON		To Computer	25 Pin Connector
RX 232	Red	Pin 3	Receive
TX 422+ / 232	Blue	Pin 2	Transmit
G (ground)	Green	Pin 7	Ground

On the top of the converter the switch on the monitor side must be set to 422 and the switch on the computer side must be set to 232.

A 120-ohm resistor must be connected, at the converter, between Common and RX 422+ / 232 on the monitor side.

If all connections are proper, when the computer is connected to the converter the 3rd LED from the top on the converter will flash every time the computer asks for information. The top LED will flash every time the monitor responds.

Figure 5a: RS485 connection with Sencon converter.

Chapter Three: Downloading Signatures

DOWNLOADING FROM A COM PORT

(If you are using the PressNet network, you will be unable to download from a com port. Please see next section.)

1. Choose Signature on the menu bar at the top left of your screen.
2. Choose Download from COM Port.
3. The Download window will appear (See Fig. 6).




Figure 6: Download window.

4. Choose the Com: Port connected to your monitor(s). (See Fig. 6).
(Note: Com 1 is set as default. See Fig. 6.)
5. Choose your monitor in the Driver menu. (See Fig. 7).
(Note: There are three choices for drivers: Quick Learn, PW and N260Load Monitors.)




Figure 7: Driver menu in the Download window.

6. Choose Address and input the proper monitor address. (See Fig. 7a).




Figure 7a: Driver menu in the Download window.

7. Click on Download. Your computer will download signatures.

DOWNLOADING FROM PRESSNET

(If you are using the PressNet network, you will only be able to download from PressNet.)

1. Choose Signature on the menu bar at the top left of your screen.
2. Choose Download from PressNet.
3. Choose a Press address in the Downloading from PressNet window. (See Fig. 8).




Figure 8: Downloading from PressNet window.

4. Click on Download. Your computer will download signatures.

SAVE A SIGNATURE AS A SIGNATURE FILE (*.SIG)

1. You may save a signature by choosing File in the menu bar and then choosing Save. You will then be able to input signature information. (See Fig. 9). The information will be displayed at the top of your screen.
2. You may view signature information later by Choosing Signature on the menu bar and then Choosing Description.
3. View or change any useful signature information. (See Fig. 9).




Figure 9: Signature Information window.

OPEN A SIGNATURE FILE

1. You may open a saved signature by choosing File on the menu bar and then choose Open.

SAVE A SIGNATURE AS A REFERENCE FILE (*.SRF)

1. You may save a signature by choosing File in the menu bar and then choosing Save. You will then be able to input signature information. (See Fig. 9). The information will be displayed at the top of your screen.
2. You may view signature information later by Choosing Signature on the menu bar and then Choosing Description.
3. Only signatures (not press curves) are saved as *.SRF

OPEN A REFERENCE FILE

1. You may open a saved signature by choosing File on the menu bar and then choosing Open.
2. You will need to load a signature file before you open a reference file.
3. Reference signatures are gray.
4. You may view a reference signature when in outer or inner, but not both.

EXIT AND SAVE VIEW

1. You may exit and save your setup view (In the View menu on the menu bar) by choosing File on the menu bar and then choose Exit and Save view.

PRINTING SIGNATURES

1. You may print signatures by choosing File on the menu bar and then choosing Print.
2. You may choose to print the Corners, Total or Data Table and may print corner on the same or different pages. (See Fig. 10).




Figure 10: Print Window

Chapter Four: Viewing Signature Windows

VIEWING EACH CORNER AND TOTAL SEPARATELY

1. To view the press Corners and Total separately, choose Window from the menu bar.
2. In Window choose Right Rear, Left Rear, Right Front, Left Front or Total.
3. If you are already viewing all five Signature windows, simply minimize each window you choose not to view.

TILE VIEW

1. Choose Window on the menu bar and then choose Tile to see all four corner signatures simultaneously. (See Fig 11).

(Note: Tile View is the default display.)




Figure 11: Signatures in Tile view.

CASCADE VIEW

1. Choose Window on the menu bar and then choose Cascade to see all four corner signatures (and the Total) Cascaded. (See Fig 12).




Figure 12: Signatures in Cascade view.

VIEW THE OUTER

1. Choose View on the menu bar and then choose Outer at the top left of your screen. This allows you to view only the outer ram signature(s). (See Fig. 13).




Figure 13: Signature in Outer view.

VIEW THE INNER

1. Choose View on the menu bar then choose Inner to view only the Inner ram signature(s). (See Fig. 14).




Figure 14: Signature in Inner view.

VIEW THE OUTER AND INNER

1. Choose View on the menu bar and then choose Outer and Inner to view both the Outer and Inner ram signature(s). (See Fig. 15).
(Note: Only for use with double action presses.)




Figure 15: Signature in Outer and Inner view.

VIEW DEGREES AND INCHES (WITH RESOLVER)

(Note: You will view milliseconds when using PW and Quick Learn monitors.)

1. To use Degrees as measurement of your signature, choose View on the menu bar and then choose Deg (Degrees).

2. To use inches as measurement of your signature, choose View on the menu bar and then choose In (Inches).

THREE WAYS TO SCALE YOUR SIGNATURES

Choose View on the menu bar to see the scaling choices.

Scale To Fit

1. Choose View on the menu bar and then choose Scale to Fit
2. This scaling will allow you to see the signatures and press curves in maximum scale. (See Fig. 16).
(Note: When viewing both outer and inner the percentage of the capacity is shown. The outer and inner use different scales).




Figure 16: Scale To Fit.

Scale Uniformly by Capacity

1. Choose View on the menu bar and then choose Scale Uniformly by Capacity.
2. This scaling will allow you to see the signatures and press curves in maximum scale. (See Fig. 17).
(Note: The outer and inner use the same scales.)




Figure 17: Scale Uniformly by Capacity.

Scale Uniformly by Highest Peak

1. Choose View on the menu bar and then choose Scale Uniformly by Highest Peak.
2. This scaling will allow you to see the signatures in maximum scale by viewing the highest peak of all corners. (See Fig. 18).




Figure 18: Scale Uniformly by Highest Peak.

Chapter Five: Using Signature Windows

HOW TO READ SIGNATURE WINDOWS




Figure 19: Signature Window.

HOW TO READ TABULAR DATA

Tabular Data

1. For complete signature data choose Tabular Data in Signature on the menu bar.

	Outer	Inner	Total	Total Max	Left Rear	Right Rear	Left Front	Right Front	CornerMax
Deg 180.00	180.00	0.00	17.19	500.00	18.55	39.06	26.37	31.25	125.00
In 0.00	0.00	0.00	158.59	700.00	66.99	21.88	12.30	60.16	175.00
Deg 182.00	182.00	0.00	113.28	500.00	18.55	39.09	25.39	30.27	125.00
In 0.00	0.00	0.00	191.41	700.00	75.20	27.34	19.14	66.99	175.00
Deg 184.00	184.00	0.00	109.38	500.00	16.60	37.11	25.39	31.25	125.00
In 0.00	0.00	0.00	224.22	700.00	87.50	39.65	24.61	75.20	175.00
Deg 186.00	186.00	0.00	105.47	500.00	15.63	36.13	24.41	30.27	125.00
In 0.00	0.00	0.00	262.50	700.00	101.17	53.32	27.34	79.30	175.00
Deg 187.00	187.00	0.00	105.47	500.00	15.63	36.13	23.44	29.30	125.00
In 0.00	0.00	0.00	300.78	700.00	114.84	66.99	32.81	84.77	175.00
Deg 189.00	189.00	0.25	101.56	500.00	14.85	35.18	23.44	29.30	125.00
In 0.25	0.25	0.00	332.86	700.00	120.31	71.09	41.02	91.60	175.00
Deg 191.00	191.00	0.00	101.56	500.00	15.63	35.16	22.46	28.32	125.00
In 0.00	0.25	0.00	317.19	700.00	116.21	68.36	41.02	92.97	175.00
Deg 193.00	193.00	0.00	105.47	500.00	15.63	36.13	23.44	28.32	125.00
In 0.00	0.25	0.00	278.91	700.00	105.27	58.79	30.08	82.03	175.00
Deg 194.00	194.00	0.00	109.38	500.00	16.60	36.13	25.39	30.27	125.00
In 0.00	0.50	0.00	196.88	700.00	87.50	38.28	12.30	61.52	175.00
Deg 196.00	196.00	0.00	113.28	500.00	17.58	39.06	25.39	31.25	125.00
In 0.00	0.50	0.00	109.38	667.19	51.95	13.67	4.10	41.02	166.80
Deg 198.00	198.00	0.00	121.09	500.00	20.51	41.02	27.34	32.23	125.00
In 0.00	0.75	0.00	43.75	595.16	20.51	5.47	4.10	16.41	146.29
Deg 200.00	200.00	0.00	125.00	500.00	21.48	39.06	30.27	33.20	125.00
In 0.00	1.00	0.00	10.94	530.47	2.73	2.73	0.00	2.73	132.62
Deg 202.00	202.00	0.00	125.00	500.00	21.48	40.04	29.30	33.20	125.00
In 0.00	1.00	0.00	-10.94	481.25	-2.73	-2.73	-2.73	-4.10	120.31
Deg 204.00	204.00	0.00	125.00	500.00	21.48	40.04	29.30	34.18	125.00
In 0.00	1.25	0.00	5.47	442.97	0.00	1.37	1.37	1.37	110.74
Deg 206.00	206.00	0.00	125.00	500.00	20.51	41.02	29.30	33.20	125.00
In 0.00	1.50	0.00	0.00	410.16	0.00	0.00	1.37	0.00	102.54
Deg 207.00	207.00	0.00	125.00	500.00	20.51	41.02	30.27	34.18	125.00
In 0.00	1.50	0.00	0.00	393.75	-1.37	0.00	1.37	1.37	99.44
Deg 209.00	209.00	0.00	128.91	500.00	21.48	41.99	31.25	34.18	125.00
In 0.00	1.75	0.00	5.47	371.88	0.00	1.37	2.73	2.73	92.97
Deg 214.00	214.00	0.00	128.91	500.00	21.48	41.99	30.27	34.18	125.00
In 0.00	2.50	0.00	0.00	317.19	-1.37	0.00	1.37	1.37	79.30
Deg 216.00	216.00	0.00	125.00	500.00	19.53	41.99	30.27	33.20	125.00
In 0.00	2.75	0.00	0.00	300.78	-1.37	0.00	0.00	0.00	75.20
Deg 218.00	218.00	0.00	125.00	500.00	20.51	40.04	30.27	33.20	125.00
In 0.00	3.25	0.00	5.47	284.38	0.00	1.37	2.73	0.00	71.09

Figure 20: Tabular Data screen.

Use Tabular Data and Signatures Together

1. You have the option to use the Tabular Data feature and signatures together. This allows you to left mouse click on the signature and move a positioning line to any desired point on the signature to receive data. (See Fig. 21)
2. To remove the data from the screen right click on the signature or press ESC.




Figure 21: Signature and Tabular Data.